

EPA ID: UTN000802664 Site Name: 5600 SOUTH 900 EAST PLUME

State ID:

Alias Site Names:

City: SALT LAKE

Refer to Report Dated: 8/14/2008

County or Parrish: SALT LAKE

1088376 - R8 SDMS

State: UT

Report Developed By:

Report Type: PRELIMINARY ASSESSMENT 001

☐ 1. Further Remedial Site Assessment Under CERCLA (Superfund) is not required because:

☒ 2. Further Assessment Needed Under CERCLA:

Higher priority for further assessment

### Discussion/Rationale:

The site includes a plume in Murray, UT where ground water samples were found to include elevated levels of tetrachloroethylene (PCE), trichloroethylene (TCE), cis-1,2-dichloroethene (DCE), and vinyl chloride (VC). There is a municipal drinking water well in the immediate area of the plume as well as 2 additional municipal wells within a mile of the plume. The closest municipal well was sampled and found to be clean. However, because of the proximity of the well to the plume, it is possible that the well could become contaminated in the deep aquifer where the well draws it's water. The extent of the plume is unknown and could potentially be affecting other nearby municipals. Therefore, further assessment is warranted under CERCLA.

Site Decision Made by: GWEN CHRISTIANSEN

Signature:

Date: 08/14/2008